			-	31/12/19		Paid/	31/12/20	2021	Paid/	31/12/21	2022	Paid/	31/12/22	2023	Paid/	Current
GRANTS SCHEDULE	UP TO 30 JUNE 2023 BY CHURCH	date	Grant £000	Creditor £000	Grants £000	released £000	Creditor £000	Grants £000	feleased £000	Creditor £000	Grants £000	released £000	Creditor £000	Grants £000	released £000	Credito £000
*All churches	TDFAS - record of all churches £100 per church	2009	0.7	0.7	£000	£000	0.7	£000	£000	0.7	£000	(0.1)	£000 0.6	£000	£000	0.6
Lydd	Repairs to other windows & west window masonry	2005	25.0	4.7		(4.7)	0.1			0.7		(0.1)	0.0			0.0
Dymchurch	Woodworm in organ and timbers	2017	2.0	1.3	(1.0)	(0.3)	0.0			0.0			0.0			0.0
East Guldeford	Installing a toilet in the church	2017	10.0	10.0	(112)	(0.0)	10.0		(10.0)							
Lydd	Fitting mesh guards in windows on southside	2018	10.0	10.0			10.0		(10.0)							
*All churches	Fifth Continent - producing audio for churches	2019	5.0	5.0			5.0		(5.0)							1
Brookland	Various items in guinguennial report	2019	23.7	23.7	4.5	(14.4)	13.8		(13.8)							-
Dymchurch	Printing guide books	2019	1.5	1.5		(1.5)										
lvychurch	Lightning conductors	2019	16.0	16.0	0.6		16.6	(2.2)	(14.4)							
lvychurch	Repairs to West door	2019	0.9	0.9	0.3	(1.2)										
lvychurch	Tower door repairs	2019	1.0	1.0		(1.0)										
Lydd	Quinquennial repairs	2019	25.0	25.0	2.1	(26.9)	0.2		(0.2)							
New Romney	Installing CCTV	2019	1.3	1.3		(1.3)										
Old Romney	New fencing	2019	10.0	10.0			10.0	(5.0)	(5.0)							
Snave	Churchyard inc. fallen tree and fencing	2019	4.1	1.4		(1.4)										
Snave	Quinquennial repairs and south east pew platform	2019	12.7	6.9		(6.9)		-			-	-		-	-	
St Mary in the Marsh	Repairs to four blocks of box pews	2019	6.0	6.0			6.0			6.0			6.0			6.0
Newchurch	Quinquennial repairs	2020.09			13.3	(13.3)										
Old Romney	Redecoration	2020.09			17.0		17.0	(0.0)	(17.0)							
Brenzett	Gable wall and roof repairs	2020.10			1.3	(1.3)										\perp
Burmarsh	Gutter clearing, fire extinguishers	2020.10			0.2	(0.2)										
lvychurch	Architect quinquennial	2020.10			0.8	(0.8)										
lvychurch	Gravestone repairs	2020.10			3.7		3.7			3.7	(0.0)	(3.7)				
St Mary in the Marsh		2020.10			7.0		7.0	(1.0)	(6.0)							
lvychurch	Roof alarm repairs	2020.12			0.8		0.8	(0.8)								
Brenzett	Architect's fees re quinquennial repairs	2021.03						1.5		1.5			1.5			1.5
Brenzett	Quinquennial repairs	2021.03						11.3	(11.3)							
Brookland	Repaint after water damage	2021.03						2.8	(2.8)							
Burmarsh	Gutter maintenance/fire extinguishers	2021.03						0.4	(0.4)							
Dymchurch	Leaking roof	2021.03						6.0		6.0		(4.3)	1.7			1.7
Dymchurch	Lightning conductor replacement	2021.03						6.1	(6.1)							
East Guldeford	Increase in above	2021.03						7.0	(7.0)							
Fairfield	Gutter maintenance, rewiring	2021.03						2.5	(2.5)							
Норе	£20,000 for refurbishment asked for	2021.03						4.5		4.5		(4.5)				
Ivychurch	Electrical test	2021.03						0.4	(0.4)							
Ivychurch	Quinquennial repairs	2021.03						9.0	(2.4)	9.0	7.4	(16.4)				
lvychurch	Renew Smartwater	2021.03						0.4	(0.4)			· · ->				
lvychurch	Water ingress	2021.03						1.7		1.7		(1.7)				
Snargate	Architect's fees	2021.03						1.0		1.0		(1.0)	-	0.5	(0.5)	
Snargate	Quinquennial repairs	2021.03						9.9	(0,0)	9.9		(9.9)		2.5	(2.5)	
St Mary in the Marsh		2021.03						2.8	(2.8)							<u> </u>
	Tower shingles	2021.03						5.0 7.2	(5.0)							<u> </u>
	Water ingress/roof repair Architect's fees	2021.03							(7.2)							+
Brookland Burmarah		2021.05						2.8	(2.8)							+
Burmarsh *Eour oburoboo	Roof damage	2021.05		<u> </u>				2.4	(2.4)	15.6		(15.6)				+
*Four churches	Mosaics	2021.10		<u> </u>				15.6	(0.6)	15.6		(15.6)				+
Brookland	Architect's fees re quinquennial repairs Architect's fees	2021.10 2021.10						0.6	(0.6)	1.5	(0.4)	(1.1)				+
lvychurch				<u> </u>				6.0	(6.0)	1.J	(0.4)	(1.1)				+
Lydd Spargato	Fitting mesh guards in windows on southside Emergency north wall repair	2021.10 2021.10		1				0.6	(6.0)							<u>+</u>
Snargate Brenzett	Quinquennial repairs	2021.10		1				1.0	(0.6)							+
Brenzett East Guldeford	Emergency tree work	2021.12		<u> </u>				0.8	(1.0)	0.8		(0.8)				+
Brookland	Tree work	2021.12						0.0		0.0	0.5	(0.6)				+
East Guldeford	Gravestone repairs	2022.03		1							4.5	(0.5)	4.5			4.5
East Guideford Newchurch	Repairs to windows	2022.03		<u> </u>							4.5		4.5 15.6			4.5
	Lead guttering	2022.03		<u> </u>							7.0		7.0			7.0
<u>St wary in the warsh</u> Burmarsh	Fire extinguisher	2022.10		1							1.0		1.0	0.1		0.1
	Gutter work	2023.03		1							0.1	(0.1)		0.1		0.1
Burmarsh Burmarsh	Trim trees	2023.03		<u> </u>				1.3		1.3	U. I	(0.1)	1.1	1.4		2.5
Burmarsn Dymchurch	Broken slates	2023.03						1.3		1.3		(0.2)	1.1	0.3	(0.3)	2.5

	ARSH HISTORIC CHURCHES TRUST E UP TO 30 JUNE 2023 BY CHURCH	Latest date	Original Grant £000	31/12/19 Creditor £000		Paid/ released £000	31/12/20 Creditor £000	-		31/12/21 Creditor £000			31/12/22 Creditor £000	2023 Grants £000	Paid/ released £000	Current Creditor £000
Dymchurch	Toilet door	2023.03						~~~~						0.2	(0.2)	
Dymchurch	Water ingress	2023.03												2.0		2.0
East Guldeford	Roof repairs	2023.03												3.0		3.0
lvychurch	Door damage	2023.03												1.0		1.0
lvychurch	Further quinquennial	2023.03												3.9	(3.9)	
Snave	Running costs	2023.03			10.0	(4.0)	6.0	5.0	(3.4)	7.6	0.7	(8.2)	0.1	10.0	(0.4)	9.8
Snargate	Various	2023.06												10.0		10.0
Snargate	Various - Architect's fees	2023.06												1.3		1.3
				125.2	60.6	(79.1)	106.8	108.1	(143.9)	70.9	35.3	(68.1)	38.1	35.6	(7.2)	66.5

-	RSH HISTORIC CHURCHES TRUST E UP TO 30 JUNE 2023 BY DATE	Latest date	Original Grant £000	31/12/19 Creditor £000	2020 Grants £000	Paid/ released £000	31/12/20 Creditor £000	2021 Grants £000	Paid/ released £000	31/12/21 Creditor £000	2022 Grants £000	Paid/ released £000	31/12/22 Creditor £000
*All churches	TDFAS - record of all churches £100 per church	2009	0.7	0.7	2000	2000	0.7	2000	2000	0.7	2000	(0.1)	0.6
*All churches	Fifth Continent - producing audio for churches	2019	5.0	5.0			5.0		(5.0)				
*Four churches	Mosaics	2021.10						15.6		15.6		(15.6)	
Brenzett	Gable wall and roof repairs	2020.10			1.3	(1.3)							
Brenzett	Architect's fees re quinquennial repairs	2021						1.5		1.5			1.5
Brenzett	Quinquennial repairs	2021						11.3	(11.3)				
Brenzett	Quinquennial repairs	2021.1						1.0	(1.0)				
Brookland	Various items in quinquennial report	2019	23.7	23.7	4.5	(14.4)	13.8		(13.8)				
Brookland	Repaint after water damage	2021						2.8	(2.8)				
Brookland	Architect's fees	2021.1						2.8	(2.8)				
Brookland	Architect's fees re quinquennial repairs	2021.10						0.6	(0.6)				
Brookland	Tree work	2022									0.5	(0.5)	
Burmarsh	Gutter clearing, fire extinguishers	2020.10			0.2	(0.2)							
Burmarsh	Gutter maintenance/fire extinguishers	2021						0.4	(0.4)				
Burmarsh	Roof damage	2021.1						2.4	(2.4)				
Burmarsh	Fire extinguisher	2022											
Burmarsh	Gutter work	2022									0.1	(0.1)	
Burmarsh	Trim trees	2023						1.3		1.3		(0.2)	1.1
Dymchurch	Woodworm in organ and timbers	2017	2.0	1.3	(1.0)	(0.3)	0.0			0.0		· · · ·	0.0
Dymchurch	Printing guide books	2019	1.5	1.5		(1.5)							
Dymchurch	Leaking roof	2021						6.0		6.0		(4.3)	1.7
Dymchurch	Lightning conductor replacement	2021						6.1	(6.1)				
Dymchurch	Broken slates	2023							х <i>с</i>				
Dymchurch	Toilet door	2023											
Dymchurch	Water ingress	2023											
East Guldeford	Installing a toilet in the church	2017	10.0	10.0			10.0		(10.0)				
East Guldeford	Increase in above	2021						7.0	(7.0)				
East Guldeford	Emergency tree work	2021.12						0.8		0.8		(0.8)	
East Guldeford	Gravestone repairs	2022									4.5		4.5
East Guldeford	Roof repairs	2022											
Fairfield	Gutter maintenance, rewiring	2021						2.5	(2.5)				
Норе	£20,000 for refurbishment asked for	2021						4.5		4.5		(4.5)	
lvychurch	Lightning conductors	2019	16.0	16.0	0.6		16.6	(2.2)	(14.4)			(
lvychurch	Repairs to West door	2019	0.9	0.9	0.3	(1.2)		(=:=)	()				
lvychurch	Tower door repairs	2019	1.0	1.0		(1.0)							
lvychurch	Architect guinguennial	2020.10			0.8	(0.8)							
lvychurch	Gravestone repairs	2020.10			3.7	(0.0)	3.7			3.7	(0.0)	(3.7)	1
lvychurch	Roof alarm repairs	2020.1			0.8		0.8	(0.8)			(0.0)	(0.17)	
lvvchurch	Electrical test	2021						0.4	(0.4)				1
lvychurch	Quinquennial repairs	2021			1			9.0	···/	9.0	7.4	(16.4)	1
lvychurch	Renew Smartwater	2021						0.4	(0.4)			,,	1
lvychurch	Water ingress	2021			1			1.7		1.7		(1.7)	1
lvychurch	Architect's fees	2021.10			1			1.5		1.5	(0.4)	(1.1)	1
lvychurch	Door damage	2023			1						1	, ···/	1
lvychurch	Further quinquennial	2023			1								1
Lydd	Repairs to other windows & west window masonry	2016	25.0	4.7		(4.7)							1
Lydd	Fitting mesh guards in windows on southside	2018	10.0	10.0	1	, ··· /	10.0		(10.0)				1
Lydd	Quinquennial repairs	2019	25.0	25.0	2.1	(26.9)	0.2		(0.2)				1
Lydd	Fitting mesh guards in windows on southside	2021.10				(_).0 /		6.0	(6.0)				1
New Romney	Installing CCTV	2019	1.3	1.3		(1.3)			(1.0)				1
Newchurch	Quinquennial repairs	2020.1	1.0		13.3	(13.3)				1 1			1
Newchurch	Repairs to windows	2020.1			10.0	(10.0)				1 1	15.6		15.6
Old Romney	New fencing	2022	10.0	10.0			10.0	(5.0)	(5.0)	1 1	10.0		10.0
Old Romney	Redecoration	2020.1	10.0	10.0	17.0		17.0	(0.0)	(17.0)	1 1			<u>† </u>
Snargate	Architect's fees	2020.1			17.0		17.0	1.0	(17.0)	1.0		(1.0)	<u> </u>
Snargate	Quinquennial repairs	2021						9.9		9.9		(9.9)	+

THE ROMNEY MAR	SH HISTORIC CHURCHES TRUST	Latest	Original	31/12/19	2020	Paid/	31/12/20	2021	Paid/	31/12/21	2022	Paid/	31/12/22
GRANTS SCHEDULE	UP TO 30 JUNE 2023 BY DATE	date	Grant	Creditor	Grants	released	Creditor	Grants	released	Creditor	Grants	released	Creditor
			£000	£000	£000	£000	£000	£000	£000	£000	£000	£000	£000
Snargate	Emergency north wall repair	2021.10						0.6	(0.6)				
Snargate	Various	2023.1											
Snargate	Various - Architect's fees	2023.1											
Snave	Churchyard inc. fallen tree and fencing	2019	4.1	1.4		(1.4)							
Snave	Quinquennial repairs and south east pew platform	2019	12.7	6.9		(6.9)							
Snave	Running costs	2023			10.0	(4.0)	6.0	5.0	(3.4)	7.6	0.7	(8.2)	0.1
St Mary in the Marsh	Repairs to four blocks of box pews	2019	6.0	6.0			6.0			6.0			6.0
St Mary in the Marsh	Timber treatment	2020.10			7.0		7.0	(1.0)	(6.0)				
St Mary in the Marsh	Regild weathervane	2021						2.8	(2.8)				
St Mary in the Marsh	Tower shingles	2021						5.0	(5.0)				
St Mary in the Marsh	Water ingress/roof repair	2021						7.2	(7.2)				
St Mary in the Marsh	Lead guttering	2022.10									7.0		7.0
				125.2	60.6	(79.1)	106.8	108.1	(143.9)	70.9	35.3	(68.1)	38.1